



XTS906 XTS907

OPERATOR MANUAL

ISSUE 2

Welcome

Thank you for choosing Parweld. This Owner's Manual is designed to help you get the most out of your Parweld products. Please take time to read the Safety precautions. They will help you protect yourself against potential hazards in the workplace. With proper maintenance this equipment should provide years of reliable service. All our systems conform to ISO9001: 2015 and are independently audited by NQA.

The entire product range carries the CE and UKCA mark, and is constructed in accordance with European and UK directives and the product specific standards where they apply.

Further Information

Parweld is the UK's leading manufacturer of MIG, TIG and Plasma torches and consumables. For more information about Parweld's complete range visit: www.parweld.com



parweld.com



[@ParweldLtd](https://twitter.com/ParweldLtd)



[ParweldTV](https://www.youtube.com/ParweldTV)



[parweld_uk](https://www.instagram.com/parweld_uk)

Contents

	Page
1.0 Safety Precautions	4
2.0 Product Description	5
3.0 Technical Specifications	5
4.0 Description of Controls	6
5.0 Installation	6
5.1 Unpacking the Water Cooler	6
5.2 Location	6
5.3 Input and Grounding Connection	7
5.4 Output Connections	7
5.5 Coolant Filling	7
6.0 Operation	8
7.0 Fault Finding	8
7.1 Routine Maintenance	8
8.0 Parts and Accessories	8
8.1 Accessories	8
8.2 Spare Parts	8
9.0 Assembly to XTM 356i and Trolley	9
10.0 EC Declaration of Conformity	10
10.1 RoHS Compliance Declaration	10
10.2 WEEE Statement	11
10.3 Statement of Warranty	11

1.0 Safety Precautions

ELECTRIC SHOCK can kill.

Touching live electrical parts can cause fatal shocks or severe burns. The electrode and work circuit is electrically live whenever the output is on. The input power circuit and machine internal circuits are also live when power is on.

Do not touch live electrical parts.

Wear dry, sound, insulating gloves and body protection.

Insulate yourself from work and ground using dry insulating mats or covers big enough to prevent any physical contact with the work ground.

Additional safety precautions are required when any of the following electrically hazardous conditions are present: in damp locations or while wearing wet clothing; on metal structures such as floors, gratings, or scaffolds; when in cramped positions such as sitting, kneeling, or lying; or when there is a high risk of unavoidable or accidental contact with the work piece or ground.

Disconnect input power before installing or servicing this equipment. Lockout/tagout input power according to Safety Standards.

Properly install and ground this equipment according to national and local standards.

Always verify the supply ground - check and ensure that input power cable ground wire is properly connected to ground terminal in the receptacle outlet.

When making input connections, attach proper grounding conductor first - double-check connections.

Frequently inspect input power cable for damage or bare wiring - replace cable immediately if damaged - bare wiring can kill.

Turn off all equipment when not in use.

Do not use worn, damaged, under sized, or poorly spliced cables.

Do not drape cables over your body.

If earth grounding of the work piece is required, ground it directly with a separate cable.

Do not touch electrode if you are in contact with the work, ground, or another electrode from a different machine.

Use only well-maintained equipment. Repair or replace damaged parts at once. Maintain unit according to manual.

Wear a safety harness if working above floor level.

Keep all panels and covers securely in place.

Clamp work cable with good metal-to-metal contact to work piece or worktable as near the weld as practical.

Insulate work clamp when not connected to work piece to prevent contact with any metal object.

FUMES AND GASES can be hazardous.

Breathing these fumes and gases can be hazardous to your health.

Keep your head out of the fumes. Do not breathe the fumes. If inside, ventilate the area and/or use local forced ventilation at the arc to remove welding fumes and gases.

If ventilation is poor, wear an approved respirator.

Read and understand the Material Safety Data Sheets (MSDS's) and the manufacturer's instructions for metals, consumable, coatings, cleaners, and de-greasers.

Work in a confined space only if it is well ventilated, or while wearing an air-supplied respirator. Always have a trained watch person nearby. Welding fumes and gases can displace air and lower the oxygen level causing injury or death. Be sure the breathing air is safe.

Do not weld in locations near de-greasing, cleaning, or spraying operations. The heat and rays of the arc can react with vapours to form highly toxic and irritating gases.

Do not weld on coated metals, such as galvanized, lead, or cadmium plated steel, unless the coating is removed from the weld area, the area is well ventilated, and while wearing an air-supplied respirator. The coatings and any metals containing these elements can give off toxic fumes if welded.

ARC RAYS can burn eyes and skin.

ARC RAYS can burn eyes and skin. Arc rays from the welding process produce intense, visible and invisible (ultraviolet and infrared) rays that can burn eyes and skin. Sparks fly off from the weld.

Wear an approved welding helmet fitted with a proper shade of filter lens to protect your face and eyes when welding or watching

Wear approved safety glasses with side shields under your helmet.

Use protective screens or barriers to protect others from flash, glare and sparks; warn others not to watch the arc.

Wear protective clothing made from durable, flame resistant material (leather, heavy cotton, or wool) and foot protection. Welding on closed containers, such as tanks, drums, or pipes, can cause them to blow up. Sparks can fly off from the welding arc. The flying sparks, hot work piece, and hot equipment can cause fires and burns. Accidental contact of electrode to metal objects can cause sparks, explosion, overheating, or fire. Check and be sure the area is safe before doing any welding.

WELDING can cause fire or explosion.

Remove all flammables within 10m of the welding arc. If this is not possible, tightly cover them with approved covers.

Do not weld where flying sparks can strike flammable material.

Protect yourself and others from flying sparks and hot metal.

Be alert that welding sparks and hot materials from welding can easily go through small cracks and openings to adjacent areas.

Watch for fire, and keep a fire extinguisher nearby. Be aware that welding on a ceiling, floor, bulkhead, or partition can cause fire on the hidden side.

Do not weld on closed containers such as tanks, drums, or pipes, unless they are properly prepared according to local regulations

Connect work cable to the work as close to the welding area as practical to prevent welding current from travelling along, possibly unknown paths and causing electric shock, sparks, and fire hazards.

Wear oil-free protective garments such as leather gloves, heavy shirt, cuffless trousers, high shoes, and a cap. Remove any combustibles, such as a butane lighter or matches, from your person before doing any welding.

FLYING METAL can injure eyes.

Welding, chipping, wire brushing, and grinding cause sparks and flying metal. As welds cool they can throw off slag. Wear approved safety glasses with side shields even under your welding helmet.

BUILD UP OF GAS can injure or kill.

Shut off shielding gas supply when not in use. Always ventilate confined spaces or use approved air-supplied respirator.

HOT PARTS can cause severe burns.

Do not touch hot parts with bare hands.

Allow cooling period before working on gun or torch.

To handle hot parts, use proper tools and/or wear heavy, insulated welding gloves and clothing to prevent burns.

MAGNETIC FIELDS can affect pacemakers.

Pacemaker wearers keep away.

Wearers should consult their doctor before going near arc welding, gouging, or spot welding operations.

NOISE can damage hearing.

Noise from some processes or equipment can damage hearing.

Wear approved ear protection if noise level is high.

Shielding gas cylinders contain gas under high pressure.

CYLINDERS can explode if damaged.

Protect compressed gas cylinders from excessive heat, mechanical shocks, physical damage, slag, open flames, sparks, and arcs. Install cylinders in an upright position by securing to a stationary support or cylinder rack to prevent falling or tipping. Keep cylinders away from any welding or other electrical circuits. Never drape a welding torch over a gas cylinder. Never allow a welding electrode to touch any cylinder. Never weld on a pressurized cylinder - explosion will result. Use only correct shielding gas cylinders, regulators, hoses, and fittings designed for the specific application; maintain them and associated parts in good condition.

Turn face away from valve outlet when opening cylinder valve.

Use the right equipment, correct procedures, and sufficient number of persons to lift and move cylinders.

Read and follow instructions on compressed gas cylinders, associated equipment, and Compressed Gas Association (CGA) recommendations.

2.0 Product Description

The XTS906 and XTS907 water coolers are designed to be integrated with MIG and TIG welding equipment to provide cooling for water cooled torches. The XTS906 unit can be either freestanding or mounted on the Parweld TR007 or TR008 trolley and connected to the XTM356i inverter. The XTS907 110 / 230V dual voltage water cooler is a freestanding water cooler.

The units can be used on small spot welding or other similar equipment up to a rating of 40KVA.

3.0 Technical Specifications

	Water Cooler Model	
	XTS906	XTS907
Input Voltage	400V AC	110 / 230 1P
Water Tank Capacity (litres)	12	12
Flow Rate (l/min)	2	2
Welding Amps Max.	350	350
Enclosure Protection	IP23	IP23
Size (LxWxH mm)	725 x 285 x 270	725 x 285 x 270
Weight (kg)	10	10
Fuse (Amps)	5	5

4.0 Description of Controls



- 1) Filler Cap
- 2) Water Tank
- 3) Water level indicator
- 4) Water return connection (Red). In
- 5) Water supply connection (Blue). Out
- 6) Mains input cable complete with 5 pin Amphenol plug.
- 7) ON OFF Switch for switching the mains supply to the water cooler on or off. Note the output of the machine is permanently on unless the on/off switch is in the off position.
- 8) Mains input 5 amp fuse for protection of the unit in case of malfunction.

5.0 Installation

Read entire installation section before starting installation.

SAFETY PRECAUTIONS

- **ELECTRIC SHOCK can kill.**
- Only qualified personnel should perform this installation.

- Only personnel that have read and understood the Operating Manual should install and operate this equipment.
- Machine must be grounded per any national, local or other applicable electrical regulations.
- The power switch is to be in the OFF position when installing work cable and electrode cable and when connecting other equipment.

5.1 Unpacking the Water Cooler

Carefully remove the unit from the packaging, we recommend you retain the packaging until the unit has been fully installed and tested in case it has been damaged in transit and has to be returned to the re-seller.

5.2 Location

Be sure to locate the unit according to the following guidelines:

In areas, free from moisture and dust.

Ambient temperature between 0-40°C.

In areas, free from oil, steam and corrosive gases.

In areas, not subjected to abnormal vibration or shock.

In areas not exposed to direct sunlight or rain.

Place at a distance of 12" (300 mm) or more from walls or similar that could restrict natural airflow for cooling.

Do not obstruct any of the cooling vents

5.3 Input and Grounding Connection

WARNING

Before starting the installation, check that your power supply is adequate for the voltage, amperage, phase, and frequency specified on the Machine nameplate.

Operate the water cooler in accordance with the voltage marked on the cabinet.

XTS906 400V 50 Hz, AC power supply.

XTS907 110 / 230V 50 Hz, AC power supply.

The input voltage must match one of the electrical input voltages shown on the input data label on the unit nameplate.

The 400V XTS906 unit comes with a 5 pin amphenol plug fitted to the mains input cable for direct connection to the socket on the rear of the XTM356i inverter. If the unit is to be used as a freestanding unit, the plug can be removed and a suitable plug fitted using the brown and blue wires for the 2 phases and green / yellow wire for the earth. See section 1.0 for safety precautions.



The 110 / 230V XTS907 unit comes without a plug fitted.

5.4 Output Connections

The Red Connection is the hot water return connection and should be connected to the red hose on the welding torch or if connected through the power source to the water drain connection.

The Blue Connection is the cold water supply connection and should be connected to the blue hose on the welding torch or if connected through the power source to the water supply connection.

Both hose connections are Type 21 Quick connections. If the water cooler is mounted away from the power source/torch, a hook up extension kit may be used, refer to the parts list.

5.5 Coolant Filling

Remove the filler cap (1) from the water tank (2) and fill the unit with Parweld UltraCool until the coolant in the water tank has reached the MAX level shown on the front of the unit. Secure the filler cap before starting the unit. There is no need to prime the pump, but on first running the pump should be allowed to run with the torch connected for 1 minute to ensure all air has been expelled from the system before welding is started. After initial running, refill the water tank to the Max level.

Warning

Operating the unit without the use of Parweld UltraCool will shorten the life of the pump and torch. UltraCool contains special additive to lubricate the pump and prevent corrosion in all parts of the system including the torch.

Glycol based fluids should not be used as they promote corrosion due to the electrical conductivity of the fluid.



6.0 Operation

Before switching on the unit ensure the header tank is full, none of the cooling vents are obstructed and the electrical connections are secure.

Move the on/off switch into the on position before operating the torch or welding plant. Allow the water cooler to run for 5 minutes to allow the air to be vented from the system if necessary un-clip the return hose from the torch at various points until the water flows through.

7.0 Fault Finding

Description	Possible cause	Remedy
Unit does not switch on	(a) The primary supply voltage has not been switched on (b) The input voltage has not been set correctly (c) Obstruction preventing rotation of the pump	(a) Switch on the primary supply voltage (b) check the input voltage matches that set on the unit (c) Have a qualified service engineer disconnect the power and then remove the cover to check rotation of the pump
Torch overheats	Low coolant flow	Check coolant level is correct, check for kinks in the hoses and system blockages. Ensure cooling vents on the unit are not obstructed. Blow out the heat exchanger.
Welding torch stops working	Low coolant flow	Check coolant level is correct, check for kinks in the hoses and system blockages. Have a service engineer check the operation of the flow switch.

7.1 Routine Maintenance

The only routine maintenance required for the water cooler is a thorough cleaning and inspection, with the frequency depending on the usage and the operating environment.

Warning

Disconnect primary power at the source before removing the cover. Wait at least two minutes before opening the cover to allow the primary capacitors to discharge.


To clean the unit, remove the screws securing the outer cover, lift off the outer cover and use a vacuum cleaner to remove any accumulated dirt and dust. The unit should also be wiped clean with a damp cloth.

	Weekly	6 months	2 Years
Check coolant level	*		
Check hoses for kinks	*		
Blow out heat exchanger		*	
Drain & replace UltraCool			*

8.0 Parts and Accessories

8.1 Accessories

Item	Stock Code	Description
NI	XTSUC	Parweld UltraCool coolant 10L
1	XTSH1	Hook up kit 1m
	XTSH3	Hook up kit 3m



8.2 Spare Parts

Item	Description	Stock Code
1	Pump (906 + 907)	7721004
2	Water Tank (906 + 907)	8831100-A
3	Heat Exchanger (906 + 907)	6081603
4	Fuse (5A) (906 + 907)	7202116
5	Power Supply PCB (906)	5496442-B

9.0 Assembly to XTM 356i and Trolley


The XTS906 water cooler can be mounted to the bottom of the XTM 356i inverter on the TR007 or TR008 trolley replacing the drawer as shown below, where it can be powered directly from the inverter.



Instructions for Replacing Drawer with Water Cooler


Step 1

Remove handle panel (1) by removing the 2 screws holding it to the rear trolley panel and the 3 screws holding it to the machine body.




Step 2

Remove 4 side screws (2) securing machine to drawer and lift machine c/w fixing brackets off drawer. Spare brackets and screws (3) are included with the water cooler if required.




Step 3

Remove 4 screws (4) securing drawer brackets to trolley base.



Step 4

Remove drawer brackets (5) from drawer and fix to underneath of XTS 906 water cooler.



Step 5

Mount water cooler complete with brackets onto trolley and secure with 4 screws (4).

Step 6

Lower machine onto water cooler and secure with the 4 side screws removed in Step 2.

Step 7

Assemble handle panel (1) back onto the top of the machine and trolley.

Step 8

Connect water cooler plug into the socket on the back of the machine.

10.0 EC Declaration of Conformity

Hereby we declare that the machines as stated below

Type: XTS906, XTS907

Conform to the EC Directives: 73/23/EEC and 89/336/EEC

European standard: EN/IEC 60974-1

This is to certify that the tested sample is in conformity with all provisions of the above detailed EU directives and product standards.



10.1 RoHS Compliance Declaration

Directive 2002/95/ec of the European Parliament

Restriction of use of certain hazardous substances in electrical and electronic equipment

Type: XTS906, XTS907

The above listed products are certified to be compliant with the rohs directive with all homogeneous component parts being controlled to ensure material contents as per the list below.

Cadmium 0.01% by weight

Lead 0.1% by weight

Mercury 0.1% by weight

Hexavalent chromium 0.1% by weight

Polybrominated biphenyl's (pbbs) 0.1% by weight

Polybrominated diphenyl ethers (pbdes) 0.1% by weight

It should be noted that under specific exempted applications, where lead is used as an alloying element the following limits are applied in accordance with the regulations.

Copper and copper alloy parts use less than 4% by weight of each homogeneous component.

Steel and steel alloy parts use less than 4% by weight of each homogeneous component.

Aluminium and aluminium alloy parts use less than 4% by weight of each homogeneous component.

Only dispose off in authorised sites for electrical and electronic waste do not dispose of with general refuse or landfill waste.

10.2 WEEE Statement



WEEE (Waste Electrical & Electronic Equipment) 2002/96/EC

In relation to implementing the legislation, Parweld has established relevant recycling and recovery methods. We have been fully compliant against the marking requirements since August 2005. Parweld is registered in the UK with the Environment agency as detailed below. For WEE compliance outside the UK please contact your supplier/Importer

Parweld is registered with a compliance scheme Official registration number is WEE/FD0255QV

When your equipment reaches the end of its service life you should return it to Parweld where it will be reconditioned or processed for recycling.

10.3 Statement of Warranty

Limited Warranty:

Parweld Ltd, hereafter, "Parweld" warrants its customers that its products will be free of defects in workmanship or material. Should any failure to conform to this warranty appear within the time period applicable to the Parweld products as stated below, Parweld shall, upon notification thereof and substantiation that the product has been stored, installed, operated, and maintained in accordance with Parweld's specifications, instructions, recommendations and recognized standard industry practice, and not subject to misuse, repair, neglect, alteration, or accident, correct such defects by suitable repair or replacement, at Parweld's sole option, of any components or parts of the product determined by Parweld to be defective.

Parweld makes no other warranty, express or implied. This warranty is exclusive and in lieu of all others, including, but not limited to any warranty of merchantability or fitness for any particular purpose.

Limitation of Liability:

Parweld shall not under any circumstances be liable for special, indirect or consequential damages, such as, but not limited to, lost profits and business interruption. The remedies of the purchaser set forth herein are exclusive and the liability of Parweld with respect to any contract, or anything done in connection therewith such as the performance or breach thereof, or from the manufacture, sale, delivery, resale, or use of any goods covered by or furnished by Parweld whether arising out of contract, negligence, strict tort, or under any warranty, or otherwise, shall not, except as expressly provided herein, exceed the price of the goods upon which such liability is based. No employee, agent, or representative of Parweld is authorized to change this warranty in any way or grant any other warranty.

Purchaser's rights under this warranty are void if replacement parts or accessories are used which in Parweld's sole judgement may impair the safety or performance of any Parweld product.

Purchaser's rights under this warranty are void if the product is sold to purchaser by non-authorized persons.

The warranty is effective for the time stated below beginning on the date that the authorized Distributor delivers the products to the purchaser. Notwithstanding the foregoing, in no event shall the warranty period extend more than the time stated plus one year from the date Parweld delivered the product to the authorized distributor.

Parweld Limited
Bewdley Business Park
Long Bank
Bewdley
Worcestershire
England
DY12 2TZ

tel. +44 1299 266800
fax. +44 1299 266900

www.parweld.com
info@parweld.co.uk