

PARWELD Limited, Bewdley Business Park, Long Bank , Bewdley , Worcs , DY12 2TZ

Product Reference & Descriptions:

P3720 , Red Welders Leather Apron, Red with White cotton webbing straps
P3721 , Natural Grey Welders Leather Apron, Natural Grey with White cotton webbing straps
P3740 , Red Welders Leather Spats , Red with Black Hook & Loop fastening
P3741 , Natural Grey Leather Spats , Natural Grey with Black Hook & Loop fastening
P3760 , Red Welders Leather Sleeves , Red with Black elasticated cuffs & arms
P3761 , Natural Grey Leather Sleeves , Natural Grey with Black elasticated cuffs & arms
P3780 , Red Welders Leather Jacket , Red with Black Hook & Loop fastening
P3781 , Natural Grey Welders Jacket , Natural Grey with Black Hook & Loop fastening

Available sizes: For items; P3740 , P3741 , P3760 , P3761 46cm (18"), P3720 ,
P3721 (24" x 36") One Size Only P3780 , P3781 Small to 4XL

Product Description:

ALL ITEMS CONSIST OF RED or NATURAL GREY SPLIT LEATHER

THESE ITEMS ARE PERSONAL PROTECTIVE EQUIPMENT BELONGING TO THE CATEGORY II DESIGN

All Products meet the requirements of the PPE Regulation 2016/425 applicable from April 21ST, 2018:
innocuousness, comfort, solidity.

It has been subject to an EU type Examination performed by:

SATRA Technology Europe Ltd (Notified Body No. 2777)

Bracetown Business Park , Clonee , DY15 YN2P, Ireland

Applicable Standards:

These products meet the requirements of the standard ISO 13688 General requirements for these types of products, BS EN ISO 11611:2015 Protective clothing for use in Welding & Allied processes and are designed to offer protection for the levels shown with ikons below:



Protection limit:

Users should be warned that these products should not be worn when there is a risk of entanglement by moving parts of machines.

These products do not contain any substances at levels that are known to, or suspected to, adversely affect user hygiene or health. The protection against risks or hazards which are not mentioned in this document is not warranted.

In the event of accidental contamination like splash of chemicals or flammable liquids on these products, wearers should withdraw and carefully remove garments. Contaminated items should be cleaned or replaced .

Intended Use:

Class 1 - Recommended for manual welding techniques with light formation of spatters and drops e.g Gas Welding, TIG welding, MIG welding, micro plasma welding, brazing, spot welding, MIMA welding (with Rutile covered electrode) for operation of machine e.g., oxygen cutting machines, plasma cutting machines, resistance welding machines, machines for thermal spraying, bench welding.

Class 2 – Recommended for manual welding techniques with heavy formation of spatters and drops e.g., MIMA welding (with basic or cellulose-covered electrode). MAG welding (with CO₂ or mixed gases), MID Welding (with high current), self-shielded flux cored arc welding, plasma cutting, gouging, oxygen cutting, thermal spraying for operation of machines e.g., in confined spaces at overhead / cutting or in comparable constrained positions. This Clothing is intended to protect against flames, molten metal spatter, radiant heat and short term accidental electrical contact.

Warnings:

For operational reasons not, all welding voltages carrying parts of arc welding installations can be protected against direct contact.

Aprons should cover the front body of the user at least from side to side seam. Additional partial body protection may be required e.g. for welding overhead, or in a knelt position.

These Garments are only intended to protect against brief inadvertent contact with live parts of an arc welding circuit, additional electrical insulation layers will be required where there is an increased risk of electric shock.

Garments are designed to provide protection against short term, accidental contact with live electric conductors at voltages up to approximately 100v D.C

Garments Should always be worn fully fastened and correctly for protection. When using additional partial protective garments, the basic garments shall meet at least Class 2 of this standard.

Storage and cleaning notice

Keep in its original packaging, under ordinary temperature and humidity conditions and in clean, covered and ventilated premises.

PPE subject to ageing:

The design performance cannot be significantly affect by ageing when stored in appropriate conditions (humidity, temperature, clean, ventilated, light).

Declaration of conformity:

Available on: www.parweld.info/document/p3780-parweld-red-leather-jacket_doc_en